


# OUTAGE CAUSES



**TXDOT Light Pole Installed Where Contact With Powerlines Occurred During High Winds. IH10 & Ranchland View**




**18-Wheeler Snagged Telecom Line, Fracturing Utility Pole & Pulling Overhead Powerlines Down. IH10 Crossing @ Les Pfeiffer. Similar incident Occurred In Raintree Woods Neighborhood**



**Lightning – damaged cross arm**



**Animals**



**Trees touching lines**